

Control Number:

Date: 04-JUNE-2021

Name of Supplier: ABCD INDUSTRIES	Address of Premises: WRITE FULL ADDRESS HERE

QC Contact Person:

Contact No.:

SKU/Product Name: L	EAF MAKING N	ACHINE
---------------------	--------------	--------

SKU Code: _____

Indent Qty: 12 Pcs

Quantity Available for PDI after 100% QC: 12 pcs

Please place ✓ or X mark in the corresponding box (numbered in the "Self Declaration QC Inspection Checklist – Seller Name – ABCD INDUSTRIES Product name – LEAF MAKING MACHINE Date – 04/04/2017.

SN	Parameters to Check				
External Inspe	External Inspection				
A1	Packaging Condition of the product is good (No Damage)				
A2	Color & Design of box/bag is as per approved standard mentioned in Deal Note				
A3	Packaging Material Quality is as per approved standard mentioned in Deal Note				
A4	Product packaging is as per specifications mentioned in Deal Note				
A5	Weight of the product with box/bag is as mentioned in Deal Note with tolerance of 2%				
A6	Volumetric weight of the product with box/bag is as mentioned in Deal Note with tolerance of 2%				
A7	MRP Label is as per Suggested Compliance Requirement by COMAPANY & Pasted on Specified Place				
A8	Bar Code is affixed and are as per COMPANY Guideline				
A9	Is single M.R.P label pasted				
A10	Cello tape put on M.R.P to avoid damage of label in transit				

Inspection Inside Box				
A11	Product inside Packaging is as per specifications mentioned in Deal Note			
A12	Complete Package Contents available (main product, accessories, manuals, leaflets, etc)			
A13	Product is not Damaged/Broken/Having Scratches			
A14	Product Appearance is Good and as per QA approved by COMPANY			
A15	Product is matching with the Creative on COMPANY Website or as received from COMPANY (if any)			
A16	Product matches with all specifications mentioned in Deal Note			
	Product having size/color matches with size/color mentioned on/with the product & size/color mentioned			
A17	on the M.R.P label			
Drop Test				
A18	Drop Test is performed (check 5 samples all should pass the drop test)			
A19	No Damage is found on outer box/packet			
A20	No Damage is found in inner contents including packaging material			
A21	Product is functioning properly after drop test			
Miscellaneous				
A22	Invoice is properly pasted (ie at specified place and covered with cello tape for Drop-Shipment)			
A23	Thank You Letter from COMPANY is Inserted Inside the Box (for Drop-Shipment Product)			

Total Qty Inspected 12 PCS Lot Status: (Ready/Not Ready) READY Date & Time of Inspection completed: 04/04/2021.

Image/Photo of Read	v Stock Attache	⊳d (V/N)· V
inaye/Filoto of Neau	y Slock Allache	- u(1/11). 1

No. of Pages in Checklist:

Other Remarks (If Any):

I hereby declare that the product stated above are 100% QC checked under the specified criteria mentioned above and the lot is ready for PDI inspection.

Name of QC In-charge & Signature

Supplier Sign & Stamp